

Message

---

**From:** Ruelas, Cynthia [RUELAS.CYNTHIA@EPA.GOV]  
**Sent:** 4/6/2020 9:48:59 PM  
**To:** Irwin, Karen [Irwin.Karen@epa.gov]  
**Subject:** FW: Risk Evaluation at Wilmington

---

**From:** Ruelas, Cynthia  
**Sent:** Friday, May 17, 2019 2:03 PM  
**To:** WILSON, PATRICK <wilson.patrick@epa.gov>  
**Cc:** Steve Armann <Armann.Steve@epa.gov>  
**Subject:** Risk Evaluation at Wilmington

Hello Patrick,

I reviewed the site investigation report for Wilmington Marine Services. They are doing redevelopment at the site and are planning on trenching certain areas of the site in preparation for subsurface utility placement. The investigation indicated that PCBs are present in soil above the action level of 1ppm in certain locations. For one particular area there were 3 boring locations at 10 ft bgs (within GW) where PCBs were detected in soil above the action level. If removal is to take place, structural integrity of the nearby retaining wall would have to be evaluated. I wanted to talk to you about risk in this area, and whether or not an LUC would be an option. I have more site information, but perhaps we can talk in more detail either over the phone or in-person when you have time – please let me know what works best for you.

Thanks!

---

Cynthia Ruelas  
Environmental Engineer  
Permits Section  
US Environmental Protection Agency Region 9  
75 Hawthorne Street, Mail Code LND-4-2  
San Francisco, CA 94105

Tel: (415) 972-3329  
Fax: (415) 947-3528  
Email: [ruelas.cynthia@epa.gov](mailto:ruelas.cynthia@epa.gov)